

HUNTING ISLAND  
BEACH EROSION – SEPTEMBER-OCTOBER, 2008  
AT SOUTH END – CABIN AREA  
PICTURES TAKEN ON 9/1/08; LABOR DAY

Submitted by Mr. Robert Rettew,  
Hunting Island Beach Preservation Association  
10/17/2008



60 Cabin Road – Once featured in a popular “coastal living” magazine – demolished 9/08



56 Cabin Road – The 5”C’s”, Croft Family – Demolished 9/08.



SC-PRT DISTRICT SUPERINTENDANT, RAY STEVENS (ON TRACTOR) AND PARK MANAGER JEFF ATKINS WORKING TO MAKE TEMPORARY REPAIR TO ROAD AND THUS FACILITATE EVACUATION OF STRANDED VEHICLES.



